PROGRESS REPORT: CALIFORNIA ABANDONED UNDERGROUND STORAGE TANK (UST) INITIATIVE

JULY 2015

Since November 2012, the California State Water Resources Control Board (State Water Board) and the U.S. Environmental Protection Agency (U.S. EPA) have been working with the Unified Program Agencies (UPAs) to identify and address a backlog of abandoned or improperly closed Underground Storage Tanks (USTs).

Next Phase of the Initiative: UST Gauge & Pump Pilot Program

After taking regulatory action, conducting investigative research, and providing one-on-one property owner outreach, the State Water Board and UPAs have obtained compliance at 205 out of the 342 Abandoned UST Sites. USTs remain out of compliance at 137 sites categorized by property owner cooperation (see chart below). The next phase of the Initiative will involve conducting field visits at selected sites to gauge the tanks to determine if product is present, measure product, and then pump out the tanks.

In July 2015, the UST Gauge & Pump Pilot Program was launched with San Bernardino County and Kern County to test a field approach for efficiently gauging and pumping tanks. Both counties have already committed resources to resolving their abandoned UST sites, together obtaining compliance at 18 facilities.

Twenty-four sites remain in these counties where abandoned

USTs either have product or the contents are unknown.


These sites are a top priority for the Initiative. The UPAs are working closely with U.S. EPA's contractor to conduct inspections, gauge tanks, and compile site-specific information to facilitate tank pumping activities. Tank pumping will be prioritized based on potential threats to sensitive populations and water resources.

205 sites have come into compliance, including the removal or closure of 159 USTs!

Tank gauging and pumping activities will shift to sites overseen by other UPAs after San Bernardino and Kern Counties are addressed.

The State Water Board will develop a separate strategy to address Out of Compliance sites with empty tanks.

The State Water Board is working with U.S. EPA and the UPAs on site-specific strategies for the 137 sites remaining Out of Compliance.



Achieving Compliance

As of June 30, 2015, the Abandoned UST Initiative:

- Obtained compliance at 60% of the 342 Abandoned Underground Storage Tank (UST) sites. See reverse for graph of progress and Figures 1-5 for maps.
- ♦ Removed or closed 159 USTs at 70 sites.
- ♦ Issued 191 Notices of Non-Compliance and followed up with 133 Notices of Violation (129 letters reissued).
- ♦ Obtained access to 25 sites, where tank surveys may be performed to locate, gauge, and remove product remaining in the tanks.
- Issued 124 courtesy follow-up letters offering free one-on-one consultations to owners.

An updated inventory and other information is available at: http://www.swrcb.ca.gov/ust/abandoned_storage.shtml

PROGRESS REPORT: CALIFORNIA ABANDONED UNDERGROUND STORAGE TANK (UST) INITIATIVE

JULY 2015

Partnering on Redevelopment

The Iglesia de Dios Israelita site is located in South Los Angeles, an environmental justice priority area. The site is owned by a church, and when the property was purchased, they did not realize there were 2 USTs that needed to be removed. In April 2015, U.S. EPA's Targeted Brownfields Assessment (TBA) Program conducted a site assessment, including the removal of the two USTs. The church plans to convert the property into a youth center with academic and recreational programs.

The TBA Program accepted 2 other Abandoned UST sites in the past year, one in Fresno County and the other in Los Angeles County.



Workshop for Property Owners




The State Water Board and U.S. EPA organized a Tank Removal Workshop for 18 property owners in December 2014, at Los Angeles County Department of Public Works.

Laura Fisher of the State Water Board gave an overview of the Initiative and discussed available State resources, while Joe Baiocco (Los Angeles County), Jose May and Greg Beach (both of San Bernardino County) described enforcement repercussions for non-compliance.

Participants broke into small groups to learn about funding programs. Since the workshop, 2 property owners applied to the Orphan Site Cleanup Fund (OSCF) and 2 property owners applied to the Replacing, Removing, or Upgrading Storage Tank (RUST) Loan and Grant Programs.

Abandoned UST Sites - Compliance Status



*Initial Abandoned UST site inventory in April 2013 included 323 sites. As of November 2013, Out of Compliance sites had already fallen to 305 sites. Nineteen additional sites were reported by UPAs in 2013-2014 for a total of 342 sites -- UPAs report additional sites as inspectors discover evidence of USTs, or after tank owners allow permits to lapse without seeking closure. The 19 "new" Out of Compliance sites reported make up 5.6% of the total site inventory tracked (342 sites).

